Westhertzanon Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/20002BR-0151/1

Work Order Type: Weatherization

Audit Name: 20002BR-0151-Audit

CLIENT INFORMATION

Client Name: 20002BR-0151 Address:

Client ID: 20002BR-0151

Alt. Client ID: Bradley County

CLIENT CONTACT INFORMATION

20002BR-0151 Applicant/Person of Record

AGENCY INFORMATION

Agency: Bradley-Cleveland Community Services Agency Agency Phone: (423) 479-4111

Address: 155 Sixth Street SE **Fax:** (423) 479-4113

Cleveland, TN 37320 *Email Address:* jswestfield@hotmail.com

Agency Contact: Birger, Perry Work Phone:

Cell Phone: (615) 566-4085

Email Address: birgerwood@aol.com

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Site Built Build approx 1987

Certified Firm/Renovator required

Client Name: 20002BR-0151 Client ID: 20002BR-0151 Alt. Client ID: Bradley County Work Order (Bid Form)

Work Order Name: WO/20002BR-0151/1 Report Run On: 5/21/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 5

Measures

Measure 2 Infi	tration Redctn			Componen	ts Bdrm	2		Inspecte
fill spac unusec	air infiltration in Bdrm 2 at the in wall framing open to I fireplace with foam. I windows with approved	attic area						
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail						7		
] []	Sub Total:	
			Measur	e Sub Total:		,	Sub Fotal:	
Field Notes:								
Measure 3 DW	H Tank Insulation			Componen	ts			Inspecte
Measure 3 DW	H Tank Insulation						Actual	Inspecte
Measure 3 DW	H Tank Insulation Description / Comment	Units		Componen		Qty		
Measure 3 DW Comment Material / Labor				Componen Estimated	<u>'</u>	Qty	Actual	
Measure 3 DW Comment Material / Labor Hot Water Equipment	Description / Comment	Units	Qty	Componen Estimated	<u>'</u>	Qty	Actual	
Measure 3 DW Comment Material / Labor Hot Water Equipment Labor	Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	Componen Estimated	<u>'</u>	Qty	Actual	
Measure 3 DW Comment # Material / Labor 1 Hot Water Equipment	Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	Componen Estimated	<u>'</u>	Qty	Actual	Inspecte
Measure 3 DW Comment # Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	Componen Estimated	<u>'</u>	Qty	Actual	
Measure 3 DW Comment # Material / Labor 1 Hot Water Equipment 2 Labor	Description / Comment DHW Tank Insulation	Units Each Each	Qty 1	Componen Estimated	<u>'</u>		Actual	

Measure 4 DV Comment	VH Pipe Insulation			Componen	ts			Inspected
Commone				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	cost for 10' of wrap							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Measure 5 Flo Comment	oor Ins. R-19			Componen		space		Inspected
Measure 5 Flo Comment # Material / Labor	oor Ins. R-19 Description / Comment	Units	Qty	Componen Estimated Unit Cost		space	Actual Unit Cost	Inspected
Comment # Material / Labor		<i>Units</i> SqFt	Qty 2650	Estimated	<u>'</u>		Actual	
Comment # Material / Labor	Description / Comment Floor Insulation -		_	Estimated	<u>'</u>		Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -		_	Estimated	<u>'</u>		Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -		_	Estimated	<u>'</u>		Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -	SqFt	2650	Estimated	<u>'</u>	Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment Floor Insulation -	SqFt	2650	Estimated Unit Cost	<u>'</u>	Qty	Actual Unit Cost	
# Material / Labor 1 Insulation Other Detail	Description / Comment Floor Insulation -	SqFt	2650	Estimated Unit Cost	<u>'</u>	Qty	Actual Unit Cost	

Measure 6 Atti	c Ins. R-30			Componen	ts Attic			Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	2650					
Other Detail								
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
	rm Windows			Componen	<i>t</i> s W-7,V	V-11,W	<i>'</i> -12	Inspected
Comment Air seal	I windows with approved	silicone		Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	SqFt	60.90					
2 Labor	Storm Window	SqFt	60.90					
3 Other	Storm Window	Each Window	3					
Other Detail								
			Measure	e Sub Total:] ;	Sub Total:	
Field Notes:								

Measure 9 Vapor Barrier Needed (Basement/CrawIspace)			Components Crawlspace					Inspected	
C	comment Use 6 m	nil plastic.							
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	SqFt	2650					
2	Labor	Labor	Hour	1					
(Other Detail			1					
L									
				Measure	e Sub Total:] :	Sub Total:	
	Field Notes:								
Į									
			Work O	rder Gra	nd Total:		Gran	d Total:	